



Open your G-Code file in Eding CNC

Start Eding CNC as normal then load the G-code file from step 1 by clicking on “Auto” (at the bottom of the Eding CNC window), followed by “Load” (the icons at the bottom of the window will change to show this button).


To load a drawing into Eding CNC, press the “Auto” button...



...followed by the “Load” button



When the file is correctly loaded you should see something like this:



If everything looks OK then proceed to the [next step](#).

From: <https://wiki.wolfcut.es/> - WMR manual

Permanent link: https://wiki.wolfcut.es/doku.php?id=open_job

Last update: 2022/08/31 17:49

